## CAMPBELL CAMPBELL EDWARDS & CONROY

PROFESSIONAL CORPORATION



ONE CONSTITUTION PLAZA THIRD FLOOR BOSTON, MA 02129 TEL: (617) 241 3000 FAX: (617) 241 5115

KEVIN P. GUICHON (617) 241-3035 kguichon20@campbell-trial-lawyers.com

July 18, 2005

Christian G. Samito, Esquire Donovan Hatem, LLP Two Seaport Lane Boston, MA 02210

RE: <u>Trans-Spec Truck Service</u>, Inc. v. Caterpillar, Inc.

U.S.D.C., Civil Action No. 04-11836-RCL

Dear Mr. Samito:

Please find enclosed documents Bates stamped S001435-S001781; S001786-S001898; S001926-S002022; S002024-S2142; S002156-S002397 and S003739-S003770. Due to the presence of sensitive confidential information pertaining to customer names and/or financial information, you will find certain redactions in the documents.

The above-referenced documents supplement Caterpillar, Inc.'s ("Caterpillar") automatic disclosure and Caterpillar Inc.'s Response to Trans-Spec Truck Service Inc.'s First Request for Production of Documents (Jan. 28, 2005), Nos. 3, 4, 18, 19, 22, 26, 27, and 28. Furthermore, Caterpillar produces these documents to supplement Caterpillar's Responses to Trans-Spec Truck Service, Inc.'s Second Set of Interrogatories, Nos. 1 and 3.

We have also enclosed a privilege log pertaining applicable to the document production. Thank you for your attention with this matter.

Best regards,

Klevin P. Guichon

KPG/kg

cc: Richard Campbell (w/o attachments)

John Grunert (w/o attachments)

Case 1:04-cv-11836-RCL Document 67-3 Filed 08/08/2005 Page 2 of 13

Thanks!

Rich Bowes


CPI Supervisor
On Highway Engine Department
(309) 578-7028 FAX (309) 578-2437
Internet E-Mail: "Bowes\_Richard\_E@Cat.com"

## CONFIDENTIAL

---- Forwarded by Beth A. Wholf/1V/Caterpillar on 05/11/2005 11:58 AM

Troy N. Guidotti/0A/Caterpillar 09/09/2004 04:32 PM

To
To
Beth A. Wholf/1V/Caterpillar@Caterpillar
Richard E. Bowes/0C/Caterpillar@Caterpillar
Steve W. Schoening/0C/Caterpillar@Caterpillar



Subject Flywheel Housing Failures

Caterpillar: Confidential Green Retain Until: 09/09/2007 Retention Category: G90 - General Matters/Administration

Team,

Here is what I found in the engine history for flywheel housing failures for the Truck Services Serial Numbers. There may be quite a few more failures but these are the ones that we have in the system and are documented. My guess is that he has had a failure on just about all of the units however, they may have been fixing them at their own facility.

Thanks,

Troy N. Guidotti
Truck Engine District Manager
Northeast Region
Hartford District Office
Office: 860-658-3434
FAX: 860-651-4118

EXHIBIT

Story

C

02/02/2004 01:32 PM

Subject: C12 / Sterling flywheel housing bolts, housing cracks

Caterpillar: Confidential Green

Retain Until: 03/03/2004

Retention Category: G90 - General

Matters/Administration

Stu,

This is an email from Al Cardoza at Southworth Milton. Al is a TEPS program manager as well as a TC. As you can see this is only one customer that is dealing with this flywheel housing issue in Sterling Chassis. We have several with this issue however, this is the largest of the group. In the hope of sparing you a long draw out email and customer list, I am providing you information from the customer that has been most effected. I appreciate any help you can provide.

Thanks Again,

Troy

---- Forwarded by Troy N. Guidotti/0A/Caterpillar on 02/02/2004 02:28 PM -----

AL CARDOZA@SMI 01/30/2004 09:45 AM

Caterpillar: Confidential Green

To: Troy N. Guidotti

Subject: C12 / Sterling flywheel housing bolts, housing cracks

Retain Until: 02/29/2004

Retention Category: G90 - General

Matters/Administration

Troy, This email is to provide you with the details which have resulted in C12 flywheel housing failures. The customer is Truck Service Inc.

South West Cutoff, Worcester, Mass. They own 30 Sterling tractors equipped with C12 engines 380 hp ,2KS vintage. The serial #s

- are as follows: 2KS27897, 2KS27904, 2KS27877, 2KS27878, 2KS27857, 2KS27931, 2KS27844,\* 2KS27936, 2KS27936, 2KS27893, 2KS27999,
- 2KS27914, 2KS27861, 2KS27791, 2KS27780, 2KS28378, 2KS28368, 2KS27955, 2KS27905, 2KS27835, 2KS27956, 2KS27953.
- 2KS28276, These engine serial numbers that are listed in red have had the flywheel housings replaced. Those in bold print have had the
- bolts repeatedly loosen. This condition of the bolts loosening and the dowel pins loosen allows the housing to shift thus allowing the
- housing to frett the back of the cylinder block. 2KS27936 has had 3 flywheel housings replaced and is in their shop in need of a 4th housing and
- the cylinder block is fretted beyond a acceptable surface.
- The operation of Truck Service Inc. is hauling tankers and dump trailers. The spec'd the trucks heavy for this sole purpose. In past they
- owned 3176 engines in Freightliners and had no problems. Also make note that each time a housing was replaced or found loose they would
- replace the engine mounts. The fact is the transmission is unsupported and creates a great deal of flexing on the flywheel housing which we
- believe is the reason the housing and bolt failure has occurred. The average mileage on these trucks is 280,000 to 325,000 miles.
- We need to discuss this on going problem and provide Truck Service with a repair that will correct the failures.



Case 1:04-cv-11836-RCL Document 67-3 Filed 08/08/2005 Page 5 of 13

Troy N.

To: Al Cardoza/POWER/SMI@SMI

Guidotti@CATERPILLA

CC

•

Subject: Re: C12 / Sterling flywheel housing bolts, housing cracks

02/03/2004 03:35 PM

---- Forwarded by Troy N. Guidotti/0A/Caterpillar on 02/03/2004 03:35 PM -----

Stuart K. Nack

02/02/2004 04:40 PM

To: Tod S. Sefton, Troy N. Guidotti

Subject: Re: C12 / Sterling flywheel housing bolts, housing cracks

Caterpillar: Confidential Green

Retain Until: 03/03/2004

Retention Category: G90 - General

Matters/Administration

Tod,


I do not recall, but I suspect this is the result of Sterling not supporting their transmission??

Troy,

Which Sterling truck is this? .....Acterra??

Bridge engines??

http://sterlingtrucks.com/PageServer.asp?Location=Home



81

8/2 Bob Carrick 440-269-5584
Truck Service -

Co-8 more? 22 trucks wants to trade.

Troy - 2 covered under warnity.

-2 failed 3 times - Another 5 need to be done. Parlied.

- #1 m in dowstime.

\_\_\_\_

Ashed for quotes Trisstate a Shrewsbury. EXHIBIT EXHIBIT

 $\cdot 82$ 

Gonto reviews

They menty—
Block & housing on 2 trucks @ milford (at.

Others - votating trucks in to describe Stud (3-4)

Stotal? Lino block or housing dange

Jay is aware (owner) Latter inspection.

Inspection on regular basis.

Fells this will constitute to be an issue.

BNIO Stelling - Cat needs to Step up to plate looking @ F/L + DDC.

WHU consider \$ on new purchase of Cat powered. Based on person hardony.


Trucks host need to be down a Tristate F/c.

7. X

85 Asked Bolo - 22 trucks at factory cost.
Plus Mr profit. Agreed - can get
rtd of trucks. New 5/4 ESC - " \$1,000 - per engine. - Check spees - 1550 lb ft. map. - Compare to other customer w/voll-oft. Sterlang pussing most + botse. HO. Penn - Bob Calbed -no returned phone call. Al - Called - Value favlure Nexa confact - list Stelne Cat icene. Root cause not get identified Bob -no Stoff, no enghes C13 - option -Cussom Should consider options Deling does not have slots open contil March OS. Also CISS Short is supply pushet be able to find single units it enstoner Pherible to take different Setys.


ofter - 5/4 + \$1,000 per unit.

- one w/ new black, new bought, + monts fathed humedakly:
Eddie Blake?





8/27



0 00000

110

1/405 Transpec Truck Service Froberter.

this Motton - mod dec plane cell.

Mark Granze - Milton Legal

Construction Materials

Have not been able to settle.

reimbursement per Caterpillar engine purchased. I 2 don't have any other specifics besides that. 3 MR. SAMITO: That's all I have. MR. GRUNERT: I think I only have one 5 auestion. Examination by Mr. Grunert: 7 0 Mr. Shoening, you were asked a question, and I think I got it down correctly, you were asked 8 9 whether -- or how you understood repairs were being 10 paid for after or around the time of the August 9, 11 2004 meeting, and I think you said that you 12 believed repairs were being taken care of per the 13 terms of the extended service coverage. What did 14 you mean by "per the terms of the extended service 15 coverage"? 16 The extended service coverage plan has specific 17 terms and conditions and limitations, and we were 18 taking care of the repairs per those terms, 19 conditions and limitations via our goodwill budget. 20 So we were paying for these repairs under goodwill 21 per the terms and conditions and limitations of the 22 extended service coverage program. 23 Does the extended service coverage program limit Q. 24 Caterpillar's obligation to repair or replacement

136

23

24

1 of a part, and exclude payment for downtime and 2 items of that type? 3

Yes, and the specifics on the extended service coverage limitations are detailed out on the back of the extended service coverage form.

But was it your understanding that Caterpillar was paying to repair or replace flywheel housings on Trans-Spec's engines under what you call goodwill?

Yes.

5

7

8

9

10 11

13

14

15

16

18 Q.

19

20

21

22

23

24

Q.

Q.

MR. GRUNERT: That's all I have.

MR. SAMITO: I have one or two more.

12 Examination by Mr. Samito:

> When you say "as per the terms of the extended service coverage," did that mean that you -- that Caterpillar was paying under goodwill but pursuant to the terms of the extended service coverage plan?

17

That is correct. Is that in effect, and correct me if I am wrong, but is that in effect that they were extending the extended service coverage -- they were following the extended service coverage plan, but doing the compensation through the goodwill budget? I can speculate, because I don't know the details,

but I believe the extended service coverage terms

STEPHEN 8/12 SQHOENING 1 306 f 293 0 5

for time and mileage were still in place, and the 1 2 engines still had extended service coverage on 3 them, but the failure, since it was not identified 4 as a Caterpillar failure per the terms and 5 conditions of the extended service coverage contract, were not being paid for under the ESC 7 program. 8 Why were the failures not being identified as a 9 Caterpillar coverage issue? 10 They were not -- the repairs themselves -- the

11 failures did not fall within the terms and conditions of the extended service coverage. I 12 13 cannot specify exactly where and why. 14 Do you have Cardoza Exhibit 2? Looking at Cardoza O. 15 Exhibit 2A, the back side of Exhibit 2A, it was that double-sided document that I had you look at; 16 17 there were some signatures on the front. Under the 18 extended service coverage, and Trans-Spec had 19 extended service coverage plus as evidenced by the 20 front page of Exhibit 2A to the Cardoza deposition, 21 from the back, it appears to be the highest 22 category here of service coverage. If you look at

the -- basically D, range of extended service, one

of the things that it says is, "The following